

Work Order ID 79913

Tuesday, February 07, 2012 12:30:57 PM

79913*Ship today*

Page 1

Item ID: D3394-3RG

Accept

N900040100Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: Lug

Start Date: 2/7/2012 Start Qty: 2.00

2

Cust Item ID:

Required Date: 2/7/2012 Req'd Qty: 2.00

2

Customer:

Reference:

Approvals:

Process Plan:

Shaw

Date:

12-02-07

Tooling:

Date:

Run Start ***NR1***

QC:

Date:

SPC (Y/N):

Date:

Stop ***NR2***Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

Draw Nbr

Revision Nbr

D3394, DEO D3394- Rev B

DEO D3394-B-2

100

0.00

100

SprayPaint

Memo

0.00

Spray Painting

Pull from stock d3394-043
remove and discard grommets

apply rock guard as per dwg D3394

*BL9180**12 - 2 - 7*

110

QC3- Inspect Part Finish

0.00

110

QC

Memo

0.00

Quality Control

12/2/9 50 0

Work Order ID 79913

79913

Page 2

Tuesday, February 07, 2012 12:30:57 PM

Item ID: D3394-3RG

Accept

N900040100

Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: Lug

Start Date: 2/7/2012 Start Qty: 2.00 ***2***

Cust Item ID:

Required Date: 2/7/2012 Req'd Qty: 2.00 ***2***

Customer:

Reference:

Approvals: Process Plan: Date:

Tooling: Date:

Run Start ***NR1***

QC: Date:

SPC (Y/N): Date:

Stop ***NR2***

Sequence ID/
Work Center ID

Operation
Description

Set Up/
Run Hours

Tool ID Tool # Plan
Code Accept Reject Reject Insp.
Qty Qty Number Stamp

120

Identify as per dwg & Stock Location: _____

0.00

120

Packaging

Memo

0.00

Packaging

130

QC21- Final Inspection - Work Order Release

0.00

130

QC

Memo

0.00

Quality Control

12/2/12 S 2

12/2/12 J

MF

12-02-07